



FICHA TÉCNICA
MÁQUINAS PARA TALLERES DE RECARGA

Termohigrómetro

Termohigrómetro

Para medir humedad y temperatura en "sala de polvo".

El Termohigrómetro es apto para el control de humedad y temperatura en "salas de polvo" empleadas para la recarga y mantenimiento de extintores. Posee Display con indicación simultaneo de hora, temperatura ambiente y humedad relativa. Función de alarma de reloj. Fijación para colgar a la pared. Display doble LCD 3 ½ dígitos. Registro de valor máximo y mínimo. Indicación de confort: COM (Temperaturas entre 20 y 26°C y Humedad entre 40 y 70%). Indicación seco: DRY (Humedad<40%). Indicación húmedo: WET (Humedad<70%). Indicación de tendencia de humedad y temperatura.

For the control of humidity and Temperature in "dust rooms".

The Thermohygrometer is suitable for the control of humidity and temperature in "dust rooms" used for the recharge and maintenance of fire extinguishers. It has Display with simultaneous indication of time, ambient temperature and relative humidity. Clock alarm function. Fixing mount to hang to the wall. Double LCD display 3 ½ digits. Registration of maximum and minimum value. Indication of comfort: COM (Temperatures between 20 and 26°C and Humidity between 40 and 70%). Dry indication: DRY (Humidity<40%). Wet Indication: WET (Humidity<70%). Indication of tendency of humidity and temperature.

MR918 CÓDIGO DE PRODUCTO PRODUCT CODE

Características técnicas / Technical features

Alto/Height	111 mm
Ancho/Width	105 mm
Profundidad / Depth	15 mm
Peso / Weight	200 g
Rango de temperatura/ Range of temperature	-50,0 a 70,0°C
Rango de humedad/ Range of humidity	10 a 90%Rr
Alimentación/Power supply	1 Pila 1.5V AAA



Incluye
certificado de
calibración

Includes
calibration
certificate